


6.0 SCHEMATIC DIAGRAM Masks

6.7 M1000

M1001 / Freedom HD



Model	Item No.	Description	Part No.
M-1001	1	BASE FRAME	M-1001-010
M-1001	2	COVER FRAME	M-1001-020
M-1001	3	SKIRT	M-1001-030
M-1001	3	SKIRT BK	M-1001-080
M-1001	4	LENS	M-1001-040
M-1001	5	METAL PARTS	M-1001-050
M-1001	6	METAL PARTS / L	M-1001-060
M-1001	7	METAL PARTS / R	M-1001-070
M-1001	8	ADJUSTER ASSY / L	MU-254L
M-1001	9	ADJUSTER ASSY / R	MU-254R
M-1001	10	STRAP	M-16-020
M-1001	11	STRAP TIE	M-27-070
M-1001	8-1	HINGE BASE	MU-254-010
M-1001	8-2	HINGE COVER	MU-254-020
M-1001	8-3	ADJUSTER BASE	MU-254-030
M-1001	8-4	ADJUSTER / L	MU-189-020L
M-1001	8-5	ADJUST BUTTON	MU189-030
M-1001	8-6	ROLLING PIPE	MU189-040
M-1001	9-1	HINGE BASE	MU-254-010
M-1001	9-2	HINGE COVER	MU-254-020
M-1001	9-3	ADJUSTER BASE	MU-254-030
M-1001	9-4	ADJUSTER / R	MU-189-020R
M-1001	9-5	ADJUST BUTTON	MU189-030
M-1001	9-6	ROLLING PIPE	MU189-040